

**HAZARD STATEMENT:**

May be harmful if swallowed.  
May cause respiratory irritation.  
May cause drowsiness or dizziness.  
Causes damage to organs through prolonged or repeated exposure.

**PRECAUTIONARY STATEMENTS:**

**Prevention:** Do not breathe dust/fume/gas/mist/vapors/spray.  
Avoid breathing dust/fume/gas/mist/vapors/spray.  
Wash skin thoroughly after handling.  
Do not eat, drink or smoke when using this product.  
Use only outdoors or in a well-ventilated area.

**Response:** Get Medical advice/attention if you feel unwell  
IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.

**Storage:** Store locked up.

**Disposal:** Dispose of contents/container in accordance with local/regional/national/international regulations.

**Danger**

Safety Data Sheet  
Number SDS-00016

**Ocal™****PATCHING COMPOUND FOR PVC****PATCHP-B  
Blue**

GID# 7TAA087990R0391

**ONE****Net Contents:****16 Fl oz. / .47 Liters****• For Use with Ocal™ Coated Conduit and Accessories**

CAREFULLY READ ALL CAUTIONS AND DIRECTIONS BEFORE USE

**WARNING**

This product can expose you to Titanium dioxide, which is known to the State of California to cause cancer. For more information, go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**by ABB****DIRECTIONS:**

1. Shake well before using.
2. Thoroughly clean and dry area to be patched.
3. Apply Ocal™ Patching Compound to damaged area with brush. Multiple layers may be used if a larger build is required.
4. Allow to dry 1 to 4 hours. For optimum results, allow to age overnight.

**Limited Warranty Applies.**Refer to: [tnb.abb.com/ecpwarranty](http://tnb.abb.com/ecpwarranty) for full warranty terms.**Supplier Identification:**

ABB Installation Products Inc.  
860 Ridge Lake Boulevard, Memphis,  
Tennessee 38120 - [electrification.us.abb.com](http://electrification.us.abb.com)  
U.S.A.

**EMERGENCY NUMBER: 1-800-535-5053****Country of Origin: United States**

©2024 ABB Installation Products Inc. and/or its related companies. All Rights Reserved.



TA04172 G