PRECAUTIONARY STATEMENTS:

Hazard statement: May cause skin irritation or allergic skin reaction, Causes serious eye damage. Harmful if inhaled. May cause damage to organs.



Prevention: Do not breathe dust fumes or vapors. Wash skin after handling. Do not eat drink or smoke while in use. Only use in well-ventilated areas. Wear appropriate personal protective equipment.

Response: IF ON SKIN: Wash with plenty of water. If skin irritation occurs: Get medical advice/ attention. Take off contaminated clothing and wash it before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention.

Storage: Store locked up.

Disposal: Dispose in accordance with local regulations.

DIRECTIONS:

- 1. Area to be patched should be clean and dry.
- Squeeze amount of material needed from tube onto area to be repaired. If needed, spread and level with putty knife.
- 3. Apply heat with heat gun, hot iron, etc., being careful not to overheat (500F max). Apply heat for 2 minutes minimum or at least 1 minute after the surface of the patch has turned glossy. (Material is a glossy liquid that turns flat with initial heat application, and then turns glossy again as heating continues).

Area can be allowed to air cool or a water quench may be used.

 Safety Data Sheet

Supplier Identification:

Number SDS-00021

ABB Installation Products Inc. 860 Ridge Lake Boulevard, Memphis, Tennessee 38120 - electrification.us.abb.com

EMERGENCY NUMBER: 1-800-535-5053

Country of Origin: United States ©2024 ABB Installation Products Inc. and/or its related companies. All Rights Reserved.